

1630 Moores Street Leeds, Alabama 35094 Tel: 205-699-6223

Fax: 205-699-2208



Avoid the following top 18 reasons why units fail Initial Inspections.

- ➤ 1. Inoperable light fixtures
- ➤ 2. Missing or inoperable smoke detectors
- ➤ 3. Utilities not in service (gas, water, electric)
- ➤ 4. Inoperable windows (missing locks or broken)
- ➤ 5. Exposed wiring
- ➤ 6. Missing discharge pipe from water heater
- > 7. Missing blanks on breaker box
- ➤ 8. Missing or damaged electrical cover plates
- ➤ 9. Missing vent fan or window in bathroom
- ➤ 10. Missing light fixture covers
- ➤ 11. GFCI close to water
- ➤ 12. Keyless lock (front & back door)
- ➤ 13. Rotting wood on exterior
- ➤ 14. Peepholes (front & back entry door)
- ➤ 15. Lack of heating system (landlord must provide heat)
- ➤ 16. Lawn care
- > 17. Bug & rodent infestation
- > 18. Chipping & peeling paint (interior & exterior)